



# TTM Pacing Follow-up Report

Printed: 19-May-2004 at 4:22 PM  
Page 1 of 1

PATIENT INFORMATION		PHYSICIAN INFORMATION	
Name:	Report(Pacemaker), Sample	Physician:	Smith, Dr. John
Patient ID:	000123456	Office:	1-800-659-8151
Phone 1:	727-536-2176	Address:	5505 Roosevelt Blvd
DOB:	6/19/1923 (80)		Clearwater, Florida
Gender:	Male		33760

DEVICE	MODEL	SERIAL #	IMPLANTED
Pacemaker	CPI Pulsar Max	629368	6/14/2001
DATA:	BOL: 100 ERI: 85 MODE: DDDR BASE RATE: 70 MAX RATE: 130 DX: ATRIAL DISSOCIATION		

TTM PACING FOLLOW-UP - 8/21/2002							
Intrinsic Rate:	70.1bpm/857ms	AV Delay:	154	Atrial PW:	0.5	Ventricular PW:	0.5
Rhythm:	A-V PACING INTERMITTENT INTRINSIC BEATS						
Magnet Rate:	100.2bpm/600ms	AV Delay:	96	Atrial PW:	0.5	Ventricular PW:	0.5
Rhythm:	FUNCTIONING NORMALLY WITH STABLE MAGNET RATE						
Comments:	PT DENIES ANY PACEMAKER RELATED PROBLEMS./JERN						
Next TTM:	6/9/2004 - 2:45:00 PM Pending - TTM Pacing Follow-up -						

## ECG STRIPS



**SEND TO**  
 Smith, Dr. John  
 5505 Roosevelt Blvd  
 Clearwater, Florida  
 33760

Signature: \_\_\_\_\_

Date: \_\_\_\_\_